### R/V Brooks McCall

# Voyage Plan

August 29, 2010

#### General

Client: BP Oil Spill Trustees
Purpose/Job: J10852 Leg 20

Area: Mississippi Canyon, GOM

From:	Fourchon, La			To:	Fourchon,	La.	
Estimated	l Duration:	5	Davs		230	Miles	

#### **Estimated Consumables**

Fuel	Required:	720	gal./day	On Board:	42,000	gal.
Lube Oil	Required:	6	gal./day	On Board:	345	gal.
Water	Required:	1000	gal./day	On Board:	47,858	gal.

# Plan Implementation

	Course to be Steered	135 degrees to 1st waypoint from Fourchon Sea Buoy	
	Distance on Course	34 nm to 1st site from Fourchon Sea Buoy	
Departure	Tidal Depth / Currents	N/A	
8/29/10	Port Clearance	N/A	
	Pilot Requirements	N/A	
	NTMs	Up to date through 34/10	
	Safe Distances	N/A	
	Prohibited Zones	Loop Terminal (Boundaries on KNav plotter, 1116A, 11358)	
Enroute	Critical Depth Areas	N/A	
	Contingency Ports	N/A	
	NTMs	Up to date through 34/10	
	Course to be Steered	215 degrees from last waypoint to Fourchon Sea Buoy	
	Distance on Course	34 nm from last waypoint from Fourchon Sea Buoy	
Est. Arrival	Pier / Anchorage	Fouchon	
9/2/10	Agent	N/A	
	Tidal Depth / Currents	N/A	
	Customs / Clearance	N/A	
	Pilot Requirements	N/A	
	NTMs	Up to date through 34/10	

Departure	1116A, 11358, 11365
Enroute-Contingency	1116A, 1115A, 11358, 11361, 11365
Arrival	1116A, 11358, 11365

# Waypoints

#	Location ID	Latitude	Longitude
1	Point North of Sea Buoy	29° 04.0625' N	90° 13.7500' W
2	WPT002	29° 01.0150' N	90° 13.5000' W
3	WPT003	29° 00.3500' N	90° 13.2100' W
4	WPT004	28° 56.5000' N	90° 11.8000' W
5	WPT005	28° 51.5000' N	90° 06.7000' W
6	WPT006	28° 49.5000' N	90° 03.5000 W
7	BM194	28* 16.7334.N	88° 55.3996 W

### **Operational Constraints**

Type of Operation	Special Considerations
Sampling etc.	SIMOPS with other vessels and operations in the area.
	'

#### **Required Reports**

#### **Daily Position Report at Midnight**

Email to:	DPR Group
LAT	Position latitude
LON	Position longitude
FC	Fuel Consumed in the Last 24 hrs.
FOROB	Fuel Remaining on Board
LOC	Lube Oil Consumed in the Last 24 hrs.
LOROB	Lube Oil Remaining On Board
WC	Water Consumed in the Last 24 hrs.
WROB	Water Remaining On Board
ETA	Estimated Time of Arrival at Next Waypoint or Port

#### **Client Reports**

Email to:	Dr. Jim Brooks, DPR Group
Responsibility of	Mike Taylor
Frequency	Each day - 24 hrs.
Format / Content	Client Specific

Email to: russellpu	tt@tdi-bi.com, russellputt@gmail.com, DPR Group
Responsibility of	Mike Taylor
Send by	Within 24 hrs. of Incident
Format / Content	TDI HSE Reporting Form

Master:	Gene Ma	jni
---------	---------	-----

# R/V Brooks McCall

### **Crew Manifest**

August 29, 2010

FD = Foc'sle Deck MD = Main Deck LL = Lower Level

#	Name	Title	Room #
1	Majni, Geno	Master	F2
2	Mitcheltree, Mark	Chief Mate	F3
3	Phillips, Kevin	2nd Mate	MD4
4	Starling, Ron	Engineer	F1
5	McCluskey, Ben	Oiler	LL16

6	Felix, Frank	A/B	LL17
7	Majni, Ann	OS	F2
8	Narcisis, Paul	Cook	MD5
9	Taylor, Mike	Party Chief	LL10
10	Clark, Paul	CTD Tech - GERG/TAMU	LL15
11	Johnson, Tracer	Winch	LL12
12	Schubauer-Berigan, Joe	EPA	MD7
13	Groen, Arie	Water Quality-Shaw	LL13
14	Susdorf, Gary	ENTRIX	LL11
15	Ascough, Rich	ENTRIX	LL11
16	Desphande, Ashok	NOAA	MD6
17	Morales, Anthony	NOAA	MD9
18			
19			
20			
21			
22			
23			